Ongoing Facilities Improvements

					$	34,000.00
Bacon ES	Life Safety Security	Smoke detector replacement	Construction		$	20,000.00
Bacon ES	Heating And Ventilation	Replace building HVAC automation control system	Construction		$	430,000.00
Bacon ES	Site Work	New playground equipment for younger children	Design	Construction	$	78,000.00
Bacon ES Total					$	590,000.00
Bauder ES	Fixtures Furniture and Equipment	Safe desks / R R N L Q J D W D G G L Q J F R D W F X E E L H V «	Install		$	65,000.00
Bauder ES	Site Work	Playground asphalt replacement	Design	Construction	$	125,000.00
Bauder ES	Site Work	Drainage on the southeast side of the building (concrete) creates frozen pond	Design	Construction	$ TJ ET Q EMC /P <	

Ongoing Facilities Improvements

Ongoing Facilities Improvements

Location	Major Category	Scope/Description	Estimated Action Year 2019	Estimated Action Year 2020	Estimated Action Year 2021	Estimated Action Year 2022	Recommended Budget as of January 2019
Shepardson ES	Interior Improvement	Toilet and sink behind a low wall in classroom with a changing station	Design	Construction			$ 47,000.00
Shepardson ES Total							$ 140,000.00
Stove Prairie ES	Fixtures Furniture and Equipment	Student desk replacement	Install				$ 17,000.00
Stove Prairie ES	General Carpentry	Lunchroom table replacement	Install				$ 6,000.00
Stove Prairie ES	Site Work	1-Build new chain link fence to secure playground. 2-Replace existing roadside wire fence with split rail fence on the road.	Design	Construction			$ 10,000.00
Stove Prairie ES	Life Safety Security	Smoke detector replacement	Design	Construction			$ 6,500.00
Stove Prairie ES	Roofing	Roof replacement			Design	Construction	$ 40,500.00
Stove Prairie ES Total							$ 80,000.00
Tavelli ES	Fixtures Furniture and Equipment	Teacher desks, file cabinets, pod furniture, lounge and conference room offices 2016	Install				$ 45,000.00
Tavelli ES	Fixtures Furniture and Equipment	New furniture for classrooms	Install				$ 11,000.00
Tavelli ES	Plumbing	Plumbing fixture replacement	Design	Construction			$ 38,000.00
Tavelli ES	Interior Improvement	Diaper changing station behind a low wall in classroom	Design	Construction			$ 6,000.00
Tavelli ES Total							$ 100,000.00
Timnath ES	Fixtures Furniture and Equipment	Replacement of worn/broken classroom furniture: desks and tables (replacement plan for 2017)	Install				$ 30,000.00
Timnath ES	Fixtures Furniture and Equipment	Round student tables, new student desks, student chairs (replacement plan for 2019)	Install				$ 32,000.00
Timnath ES	General Carpentry	Sun-blocking shades or working blinds for all classrooms (This would address both our heat issue and it is a safety priority)	Install				$ 105,000.00
Timnath ES	Life Safety Security	Smoke detector replacement	Install				$ 13,000.00
Timnath ES	Interior Improvement	Toilet and sink behind a low wall in classroom with a changing station	Design	Construction			$ 50,000.00
Timnath ES	TBD	Unallocated funds from completed projects	TBD				$ 280,000.00
Timnath ES Total							$ 510,000.00
Traut ES	General Carpentry	Blinds for almost all windows in the building (including exterior door windows) are past or near end-of-life. They are bent, grime-aged, and difficult to open/close	Install				$ 15,000.00
Traut ES	ADA Compliance	Curb cut repair	Construction				$ 13,000.00
Traut ES	Life Safety Security	Horns and strobe installation	Design	Construction			$ 50,000.00
Traut ES	Site Work	Grading, water/ice damage - Part of the issue in door failure is due to inadequate drainage by entryways - water tends to pool by downspouts and grades are barely, if at all directed away from the building in many areas. In times of heavy precipitation or snowmelt, this water backs up into classrooms, damaging rugs and walls. In addition, these pools are stagnant such that they freeze over in winter, creating significant morning hazards that require frequent applications of salt and non-skid materials, exacerbating the rust and jamming problem of the doors. We also have an issue with ice along the whole north sidewalk - an area which is in the shade all winter. Of particular concern is the icy patch by our north double doors entrance, where water drips off the awning and creates a persistent icy spot with its associated hazards. We have had a number of spills at that location, and it is only a matter of time before someone gets seriously injured.	Design	Construction			$ 52,000.00
Traut ES	Interior Improvement	Two toilets and sinks behind low walls in classrooms with two changing stations					

Ongoing Facilities Improvements

Location	Major Category	Scope/Description	Estimated Action Year 2019	Estimated Action Year 2020	Estimated Action Year 2021	Estimated Action Year 2022	Recommended Budget as of January 2019
Traut ES Total							$ 1,370,000.00
Warehouse 5	ADA Compliance	No ADA compliant toilet. Modify existing toilet to be ADA compliant.	Construction				$ 10,000.00
Warehouse 5 Total							$ 10,000.00
Webber MS	Electrical	Light fixture in lobby (only original ones left in building)	Install				$ 8,000.00
Webber MS	Bleachers	New bleachers in main gym	Design	Construction			$ 88,000.00
Webber MS	General Carpentry	Cafeteria tables	Design	Construction			$ 73,000.00
Webber MS	Life Safety Security	Horns and strobe installation	Design	Construction			$ 81,000.00
Webber MS Total							$ 250,000.00
Wellington MS	TBD	School is being replaced	TBD				$ -
Wellington MS Total							$ -
Werner ES	Fixtures Furniture and Equipment	Additional Technology	Install				$ 20,000.00
Werner ES	Flooring	Gym floor refinishing	Install				$ 20,000.00
Werner ES	Interior Improvement	Darkening classroom project	Design	Construction			included in $20k technology budget
Werner ES	Life Safety Security	Fire alarm system replacement	Design	Construction			$ 55,000.00
Werner ES	Plumbing	Upgraded sinks	Design	Construction			$ 15,000.00
Werner ES	Site Work	Concrete replacement	Design	Construction			$ 40,000.00
Werner ES Total							$ 150,000.00
Zach ES	Renovation	Permanent addition	Construction				
Zach ES Total							$ -

Subtotal	$	39,782,000.00
Reserves	$	218,000.00
Total	$	40,000,000.00